

2023 MAZDA CX-8 2.5 25S Grand Journey 4WD		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
6BA-KG5P	2,488 cc		
YEAR / REG.	MILEAGE		
2023/07	20,000 km		
DOORS	SEATS		
5	7		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
White	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
KG5P-353906	493 × 185 × 173 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Cruise Control		Side Camera	
Back Camera		Adaptive Cruise Control	
Front Camera		360° Camera	
Navigation System			
INSPECTOR REPORT			
Alloy wheel scratches/scuffs, underbody rust, minor scratch repair, steering wheel wear.			

初年度登録 R5 / 7月	メーカー マツダ	D/A検査 S	P/Dチヤウボ SUW/Kロカン	評価点 4		
	車名 C X - 8	グレード 2.5 25S グランドジャーニール 4WD レーダークルーズ/360°カメラ(衝突軽減ブ)	駆動方式 2WD (B)			
車種 自家用・その他（ ）	排気量 2500 CC	型式 6BA-KGSP	運転形式	内装 A・③・C		
年式 - 年 [] 月 [] 日 []	類別 乗用車 ハイブリッド ()	ディーゼル	後部座席用品（保証書・取扱説明書等）			
走行 [][]万 [][]千 [][]百 [][]十 [][]円	シフト フロア 6 AT					
外観色 ログラムホワイトプレミアムメタリック	カラーNo. AG・GG・WG・()	新車のみの〇印を記入				
()	内装色	最大積載重量 5 t	サンルーフ	革シート		
リム左・右 左：(B) ディーパー・運行	タイヤサイズ別 14,660円	キーリング	ナビ付	クロス		
セールのポイント						
ナビ、TV、ETC、シートヒーター、全周囲カメラ、HUD、BSM、パワーシート						
検査記入欄						
AWキズケズレ、下廻りサビ、小キズ補修、ハンドルスレ						
修復歴						
有。(E)						
A キズ	B ヒコギザハミ	C キズヘンタカ	E 傷痕ゼンセン	F ガラスキズ		
G 腐蝕跡	H サビ	I 変質	J 交換機	KX 欠損済		
事故別記				名義人		
車体番号	KG5P-353906					
FW	L	M	N	O		
内装	S	T	U	V		