

2023 MercedesBenz Benz GLB Class GLB200d 4MATIC		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-247613M	DISPLACEMENT 1,949 cc		
YEAR / REG. 2023/11	MILEAGE 18,973 km		
DOORS 5	SEATS 7		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE SUV		
CHASSIS NO. W1N2476132W330430	DIMENSIONS (L X W X H) 464 × 184 × 170 cm		
SALES POINTS			
Alloy Wheels Leather Seats Pre-Collision Braking Parking Assist (Auto Steering) Side Camera Navigation System		Roof Rails Power Tailgate Adaptive Cruise Control Front Camera Back Camera	
INSPECTOR REPORT			
Exterior: Overall light A. Interior: Steering wheel scuff A, seat scuff and wear A, child seat marks, headliner scuff A, trim A.			

初年度登録 R5 / 11月	メーカー メルセデス・ベンツ 車名	ドア数 5	ボディ形状 SUV/クロカン	評価点 4.5
	グレード GLB	GLB 200 d 4マテック		駆動方式 2WD ⓧD
車種 自家用 ・ その他 ()	排気量 1940 cc	型式 3DA-247613M	通年式 正	内装 A ・ Ⓐ ・ C
車検 8年11月 / 検出	燃料 ガソリン ハイブリッド ()	モデル メルセル	検出項目品 (ⓧ 書き・取捨指図書 等)	
走行 18,973 km	エンジン AT			
外装色 ホワイト (144)	カラーメタ AG ・ GAG ・ WAG ・ ()	新着品のみの〇印を記入		
()	内装色 その他	乗客定員 7人	PS	サンルーフ
左・(R) 右・(L) 輸入区分	走行	20,170円	ABS ナビ TV キーレス	
セルスポイント				
360° ビューカメラ シートリクター 置くだけ充電 BSM				
検査記入欄				
月番 令和5年A	A キズ U ヘッドランプ B キズ/ヘッパ X 後部バンパー Q ガラスキズ W 補修傷 S サビ C 腐食 A 交換機 XX 交換済			
内装 パイプレスシ、A シートスリ、ヘッドリ、A、チャイルドシート兼 実用クロスシ、A トリムA	登録料 月 日 家でに各費で各する 形式番号 W1N2476132W330430			
PW (トコ) (丸)	ワレ	内装	小 (丸) (丸)	エアロ
内装 (ゴク)	シミ ヤブレ	コガ コガ灰 オードイオ	エアロ	ノズル
最大積載量 0kg				