

2023 MINI 5HB Cooper SD Classic Trim		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3DA-XV20MW	1,995 cc		
YEAR / REG.	MILEAGE		
2023/06	11,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Gray	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WMW22DV0802U29651	404 × 173 × 145 cm		
SALES POINTS			
Alloy Wheels		Leather Seats	
Pre-Collision Braking		Parking Assist (Auto Steering)	
Back Camera		Navigation System	
INSPECTOR REPORT			

初年度登録		メーカー		ドア数		ボディ形状		評価点																																									
R5 / 6月		MINI		5		コンパクトハッチバック		5																																									
車名		MINI		グレード		クーパー・SD クラシック・トリム		駆動方式 2WD 4WD																																									
車種 自家用 ・ その他 ()		排気量 1995 cc		型式 3DA-XV20MW		選択式 内装		A・B・C																																									
車検 10年6月		燃料 ガソリン		変速機 5速MT		後期選り品 ()		等																																									
走行 11万000km		シフト フロア 8 AT		スペアキー																																													
外装色 ルーフトップ・グレー・メタリック		カラーNo.		エンジン A・A・D・W・A・C ()		装備品のみ O印 を記入																																											
()		内装色		標準定員 5人		☐ PS ☐ AS ☐ AV サルーフ ☐ TV ☐ モーニング																																											
左・右・輸入 左・右・輸入		ディーゼル		走行		リサイクル料		5,750円・国庫税																																									
セールスポイント		本革シート/キーレスエントリー/A B S 5速転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/メモリーナビ他/衝突被害軽減ブレーキ/ワンオーナー/TC/アイドリングストップ/オートキー/盗難防止システム/オートクルーズコントロール/LEDヘッドライト/横滑り防止装置 (ESC) /シートヒーター/ミュージックプレーヤー/接続可/バックカメラ/障害物センサー/パーキングアシスト/M Tモード付き/定期点検記録簿																																															
検査記入欄		修復歴 有 ()																																															
検査結果		<table border="1"> <tr> <td>A</td><td>欠点</td><td>U</td><td>へき点</td><td>レ</td><td>欠点</td><td>P</td><td>欠点</td><td>Q</td><td>欠点</td></tr> <tr> <td>W</td><td>修繕</td><td>S</td><td>ヤビ</td><td>C</td><td>腐食</td><td>X</td><td>交換</td><td>XX</td><td>交換</td></tr> <tr> <td colspan="2">登録地</td><td colspan="2">月</td><td colspan="2">日</td><td colspan="4">まで</td></tr> <tr> <td colspan="2">車体番号</td><td colspan="8">WMW22DV0802U29651</td></tr> </table>								A	欠点	U	へき点	レ	欠点	P	欠点	Q	欠点	W	修繕	S	ヤビ	C	腐食	X	交換	XX	交換	登録地		月		日		まで				車体番号		WMW22DV0802U29651							
A	欠点	U	へき点	レ	欠点	P	欠点	Q	欠点																																								
W	修繕	S	ヤビ	C	腐食	X	交換	XX	交換																																								
登録地		月		日		まで																																											
車体番号		WMW22DV0802U29651																																															
PW		シボ		ワレ		シボ		シボ																																									
内装		シボ		ワレ		シボ		シボ																																									