

2023 Mitsubishi Delica D5 P		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3DA-CV1W	2,267 cc		
YEAR / REG.	MILEAGE		
2023/09	23,000 km		
DOORS	SEATS		
5	8		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Other	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
CV1W-4020565	480 × 180 × 188 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Both...	
Power Tailgate		Pre-Collision Braking	
Adaptive Cruise Control		Front Camera	
Side Camera		Back Camera	
360° Camera		Navigation System	
INSPECTOR REPORT			
Exterior: Noticeable scratches and dents have been repaired, but minor scratches and dents remain. Interior: Some noticeable stains are present in parts. Repair history: No abnormalities found in the frame.			

R5/9月 R5年 月 日 三菱 デリカD：5 平成何年 5 D 何月何日	
R5年 月 日 三菱 デリカD：5 平成何年 5 D 何月何日	
R5年 月 日 三菱 デリカD：5 平成何年 5 D 何月何日	
R5年 月 日 三菱 デリカD：5 平成何年 5 D 何月何日	
R5年 月 日 三菱 デリカD：5 平成何年 5 D 何月何日	
R5年 月 日 三菱 デリカD：5 平成何年 5 D 何月何日	
R5年 月 日 三菱 デリカD：5 平成何年 5 D 何月何日	
R5年 月 日 三菱 デリカD：5 平成何年 5 D 何月何日	
R5年 月 日 三菱 デリカD：5 平成何年 5 D 何月何日	
R5年 月 日 三菱 デリカD：5 平成何年 5 D 何月何日	
R5年 月 日 三菱 デリカD：5 平成何年 5 D 何月何日	
R5年 月 日 三菱 デリカD：5 平成何年 5 D 何月何日	
R5年 月 日 三菱 デリカD：5 平成何年 5 D 何月何日	
R5年 月 日 三菱 デリカD：5 平成何年 5 D 何月何日	
R5年 月 日 三菱 デリカD：5 平成何年 5 D 何月何日	
R5年 月 日 三菱 デリカD：5 平成何年 5 D 何月何日	
R5年 月 日 三菱 デリカD：5 平成何年 5 D 何月何日	
R5年 月 日 三菱	