

2023 PEUGEOT PEUGEOT 408 GT		OVERALL	
		6	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3BA-P54HN05	1,199 cc		
YEAR / REG.	MILEAGE		
2023/12	9,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Green	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
VR3FPHNSTPY536409	470 × 185 × 150 cm		
SALES POINTS			
Alloy Wheels		Leather Seats	
Power Tailgate		Power Seats (Front)	
Pre-Collision Braking		Adaptive Cruise Control	
Front Camera		Side Camera	
Back Camera		360° Camera	
Navigation System			
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

車種	メーカー	ドア数	ボディ形状	評価点					
R5	プジョー	5	コンパクト/ハッチバック	6					
12月	408	GT 兼 標準本革シート	2WD						
		シートヒーター AppleCarPlay	4WD						
車庫	自家用・その他 ()	排気量	1200 cc	型式					
			3BA-P54HN05	内装					
				A・B・C					
年	8	月	12	日					
走行	9	万	000	km					
外装色	オプセッション・ブルー	カラーNo.							
		エンジン	Qd・AAG・WAG・()						
		乗車定員	5人						
左・前・後・右	左・前・後・右	左・前・後・右	左・前・後・右	左・前・後・右					
18,220円									
セラーズポイント									
本革シート/キーレスエントリー/ABS/運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/メモリーナビ/衝突被害軽減ブレーキ/ETC/スマートキー/盗難防止システム/オートクルーズコントロール/LEDヘッドライト/横滑り防止装置(ESC)/パワーシート/シートヒーター/電動リアゲート/DVD再生/ミュージックプレイヤー接続可/CD/全周カメラ/フロントカメラ/サイドカメラ/バックカメラ/障害物センサー/Mモード付き/定期点検記録簿									
検査記入欄									
修復歴									
有・無									
A	キズ	U	ヘコみ/凹み	B	キズ/ヘコみ	P	色あせ/汚れ	G	ガラス/キズ
W	腐食/錆	S	サビ	C	腐食	X	交換済	XX	交換済
名義中									
月 日 まで									
VR3FPHNSTPY536409									
内装	ボディ	シロ	サブリ	コグ	コグ	コグ	コグ	コグ	コグ
内装	ボディ	シロ	サブリ	コグ	コグ	コグ	コグ	コグ	コグ