

2023 Suzuki Jimny XL		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3BA-JB64W	DISPLACEMENT 658 cc		
YEAR / REG. 2023/08	MILEAGE 63,000 km		
DOORS 3	SEATS 4		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Kei		
CHASSIS NO. JB64W-303995	DIMENSIONS (L X W X H) 340 × 148 × 173 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
INSPECTOR REPORT			
Exterior: Noticeable scratches and dents have been repaired, but small scratches and dents remain. Interior: Some noticeable dirt, etc., is partially present. Repair History: No abnormalities in the structural parts.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録
R5/8月

メーカー
スズキ

車名
ジムニー

グレード
◆XL

ボディ形状
軽四

評価点
4

車種
自家用

駆動方式
右

型式
3BA-JB64W

排気量
660

燃料
ガソリン

内装
B

年
-

月
-

日
-

走行距離
63,000

マイル
0

4WD

AC

重量
Kg

外装色
シャアンバリーメタリック

カラーNo.
()

リサイクル料

6,180円

車両番号
JB64W-303995

()

シフト
フロア

AT

乗車定員
4

長さ
cm

幅
cm

高さ
cm

検行送り品
(保証書・取扱説明書等)

ディーラー
K3222600603

装備
①②③④⑤⑥⑦⑧⑨⑩⑪⑫⑬⑭⑮⑯⑰⑱⑲⑳㉑㉒㉓㉔㉕㉖㉗㉘㉙㉚㉛㉜㉝㉞㉟㊱㊲㊳㊴㊵㊶㊷㊸㊹㊺㊻㊼㊽㊾㊿

セールスポイント
フルフラット荷重り防止装置(ESC)
運転席エアバック/助手席エアバック/サイドエアバック/衝突被害軽減ブレーキ/安全安全ボディ4WD/アイドリングストップ/シートヒーター

常定員記入欄

ディーラー
K3222600603

販売店
2023年7月8日

内装
2023年7月8日

外装
2023年7月8日

走行距離
2023年7月8日

マイル
2023年7月8日

4WD
2023年7月8日

AC
2023年7月8日

重量
2023年7月8日

長さ
2023年7月8日

幅
2023年7月8日

高さ
2023年7月8日

車両状態の図解
小 A4サイズ未満 中 A4サイズ未満 大 A4サイズ以上

車両状態の図解
小 A4サイズ未満 中 A4サイズ未満 大 A4サイズ以上

ボグダメージレベルに関する注意事項
最小は0の場合のみ
0は1
1は2
2は3
3は4
4は5
5は6
6は7
7は8
8は9
9は10
10は11
11は12
12は13
13は14
14は15
15は16
16は17
17は18
18は19
19は20
20は21
21は22
22は23
23は24
24は25
25は26
26は27
27は28
28は29
29は30
30は31
31は32
32は33
33は34
34は35
35は36
36は37
37は38
38は39
39は40
40は41
41は42
42は43
43は44
44は45
45は46
46は47
47は48
48は49
49は50
50は51
51は52
52は53
53は54
54は55
55は56
56は57
57は58
58は59
59は60
60は61
61は62
62は63
63は64
64は65
65は66
66は67
67は68
68は69
69は70
70は71
71は72
72は73
73は74
74は75
75は76
76は77
77は78
78は79
79は80
80は81
81は82
82は83
83は84
84は85
85は86
86は87
87は88
88は89
89は90
90は91
91は92
92は93
93は94
94は95
95は96
96は97
97は98
98は99
99は100

クオリティグレード説明
外装気になるキズやヘコミは補修済みですが、小さなキズやヘコミが残っています。
内装気になる汚れ等が、部分的にあります。
修復歴:骨格部位に異常はありません。