

2023 Suzuki XBEE Hybrid MV		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
MN71S	996 cc		
YEAR / REG.	MILEAGE		
2023/01	20,600 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Hybrid (Petrol)	Right		
EXTERIOR COLOR	BODY TYPE		
Green	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
MN71S-306195	376 × 167 × 171 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Adaptive Cruise Control			
INSPECTOR REPORT			
Core support XX, left front side member and bumper panel distorted, left front inner panel, left front fender and stay distorted, various scratches and dents.			

ORIGINAL JAPANESE AUCTION SHEET

年式 R5 1月	メーカー スズキ	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 R
車名 クロスビー	グレード ハイブリッドMV	駆動方式 2WD	4WD	
車種 自家用・その他	排気量 1000 cc	型式 MN71S	通称 型式	内装 A・B・C
車検 - 年 月	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書等)	
走行 20,600 km	フロア 6 AT			
外装色 タフカーキパールメタリックII	カラーNo. A0・AAG・WAG・	エアコン	新着品のみ O印 を記入	
5人	5人	サンルーフ	高シート	
7,450円	7,450円	ナビ	TV	ス
セールスポイント				
ディスプレイオーディオ バックカメラ Bluetooth接続 ETC USB接続 レーダークルーズコントロール シートヒーター 後方ゾナー レーンキープアシスト スマートキー				
検査記入欄				
コアサポートXX 左FサイドメンバーBPEZミ 左Fインナーパネル 左Fフェンダーアサシスト 各種ス				
修理歴				
A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスズレ W 雨傷跡 S サビ C 腐食 X 交換部 XX 交換済				
名義中				
月 日 までに名義できる方				
車体番号 MN71S-306195				
FW トボ石	傷A	フレ	外装	小
内装	コガレ	シミ	ヤブレ	コガ
コガ穴	オーディオ穴	スレ	取崩	傷
高さ	高さ	高さ	最大積載量	kg