

| 2023 Toyota Alphard Z                                                                                                                                                                                           |  | OVERALL               |          |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|-----------------------|----------|
|                                                                                                                                                                                                                 |  | EXTERIOR              | INTERIOR |
| MODEL CODE<br>3BA-AGH45W                                                                                                                                                                                        |  | 4                     |          |
| YEAR / REG.<br>2023/10                                                                                                                                                                                          |  | -                     |          |
| DOORS<br>5                                                                                                                                                                                                      |  | -                     |          |
| DRIVETRAIN<br>4WD                                                                                                                                                                                               |  |                       |          |
| FUEL<br>Petrol                                                                                                                                                                                                  |  |                       |          |
| EXTERIOR COLOR<br>Other                                                                                                                                                                                         |  |                       |          |
| CHASSIS NO.<br>AGH45-0001181                                                                                                                                                                                    |  |                       |          |
| SALES POINTS                                                                                                                                                                                                    |  |                       |          |
| Alloy Wheels                                                                                                                                                                                                    |  | Sunroof               |          |
| Glass Roof                                                                                                                                                                                                      |  | Leather Seats         |          |
| Power Sliding Doors (Both Sides) (Both...                                                                                                                                                                       |  | Power Tailgate        |          |
| Power Seats (Front)                                                                                                                                                                                             |  | Pre-Collision Braking |          |
| Adaptive Cruise Control                                                                                                                                                                                         |  | Front Camera          |          |
| Side Camera                                                                                                                                                                                                     |  | Back Camera           |          |
| 360° Camera                                                                                                                                                                                                     |  | Navigation System     |          |
| INSPECTOR REPORT                                                                                                                                                                                                |  |                       |          |
| Exterior: Noticeable scratches and dents have been repaired, but minor ones remain. Interior: The cabin is clean with minimal noticeable stains. Repair history: No abnormalities in the structural components. |  |                       |          |

[illegible]