

|                             |                        |                                 |          |
|-----------------------------|------------------------|---------------------------------|----------|
| 2023 Toyota Corolla Cross Z |                        | OVERALL                         |          |
|                             |                        | 4                               |          |
|                             |                        | EXTERIOR                        | INTERIOR |
|                             |                        | -                               | -        |
| MODEL CODE                  | DISPLACEMENT           |                                 |          |
| 4BA-MXGA10                  | 1,986 cc               |                                 |          |
| YEAR / REG.                 | MILEAGE                |                                 |          |
| 2023/12                     | 67,759 km              |                                 |          |
| DOORS                       | SEATS                  |                                 |          |
| 5                           | 5                      |                                 |          |
| DRIVETRAIN                  | TRANSMISSION           |                                 |          |
| 2WD (FF)                    | AT                     |                                 |          |
| FUEL                        | STEERING               |                                 |          |
| Petrol                      | Right                  |                                 |          |
| EXTERIOR COLOR              | BODY TYPE              |                                 |          |
| Black                       | SUV                    |                                 |          |
| CHASSIS NO.                 | DIMENSIONS (L X W X H) |                                 |          |
| MXGA10-1000892              | 449 × 183 × 162 cm     |                                 |          |
| SALES POINTS                |                        |                                 |          |
| Alloy Wheels                |                        | Roof Rails                      |          |
| Power Tailgate              |                        | Leather Seats (Leather, Fabric) |          |
| Pre-Collision Braking       |                        | Adaptive Cruise Control         |          |
| Back Camera                 |                        | Navigation System               |          |
| INSPECTOR REPORT            |                        |                                 |          |
| Minor scratches on exterior |                        |                                 |          |

[illegible]