

2023 Toyota GR86 RC		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3BA-ZN8	DISPLACEMENT 2,387 cc		
YEAR / REG. 2023	MILEAGE 9,500 km		
DOORS 2	SEATS 4		
DRIVETRAIN 2WD (FR)	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Coupe		
CHASSIS NO. ZN8-028209	DIMENSIONS (L X W X H) 426 × 177 × 131 cm		
INSPECTOR REPORT			
4-point seat belts and tow hooks are detached. Front windshield has stone chips. Front bumper has a dent with a scratch on its center tip, and small scratches on its underside. Right front fender, left and right doors, left and right door mirrors, and all four wheels have scratches. The left side step has lifted parts and a large scratch.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R5 / 一月	メーカー トヨタ	ドア枚数 2	ボディ形状 クーペ	評価点 4
車名 GR86	グレード RC	駆動方式 2WD 4WD		
車種 自家用・その他 ()	排気量 2380 CC	型式 3BA-ZN8	通称 型式	内装 A・B・C
車検 - 年 / 月 / 日	燃料 ガソリン ハイブリッド ()	ディーゼル ()	後日添付品 (保証書・取扱説明書 等)	
走行 9,500 マイル	シフト MT			
外装色 クリスタルホワイトパール	カラーNo. ()	エンジン Aa・AAG・WAG・()	装備品のみ O印 を記入	
内装色 ()	必要定員 人	PS	PW	AW
左・右 左・右	輸入 区分	ディーラー 進行	エアバック	ABS
10,660円・預託金		ナビ	TV	キーレス
セールスポイント		修復歴 有・無		
検査記入欄		A キズ U ヘビイサレ B キズ・ヘビイ P 色あせ・ボケ Q ガラスキズ W 補修跡 S サビ C 腐食 X 交換品 XX 交換所		
4点シートベルトと牽引フックは外してお渡します。 Fガラスに飛び石、Fバンパー中央先端に傷を伴う凹み、右Fフェンダー、 左右ドア、左右ドアミラー、両Fと左Rホイールに傷がございます。 左サイドステップにはパーツの浮きと大きめの傷がございます。また、F バンパー下面に小さな傷がございます		名義中 登録No. 月 日 までに名義できる方 車検 番号 ZN8-028209		
PW (トビ) ()	ワレ	外装 (A)・(B) (A)・曲 A・ワレ	シリアル No.	
内装 (ゴキ) シミ ヤブレ	コガ	コガ穴 オーディオ穴 ()	車幅 426 cm	車高 177 cm
			最大積載量 131 cm	Kg