


2023 Toyota Harrier PHEV Z		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
6LA-AXUP85	2,487 cc		
YEAR / REG.	MILEAGE		
2023/02	64,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Hybrid (Petrol)	Right		
EXTERIOR COLOR	BODY TYPE		
Other	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
AXUP85-0001734	474 × 186 × 166 cm		
SALES POINTS			
Alloy Wheels		Glass Roof	
Power Tailgate		Power Seats (Front)	
Leather Seats (Leather)		Pre-Collision Braking	
Adaptive Cruise Control		Front Camera	
Side Camera		Back Camera	
Navigation System		JBL Premium Sound System (9 Speaker...	
INSPECTOR REPORT			
Stone chip on windshield, dirt/stains on interior.			

初年度登録 R5 /		メーカー トヨタ		ドク板量 5		原付容量 SUW/クロカン		評価点 8																	
2月		車名 ハリアー-PHEV		グレード Z		燃費区分 2WD 160		R																	
車種 自家用・その他 ()	排気量 2480	CC cc	型式 6LA-AXUP85	運転形式	所装 A・③・C																				
車検 10年2月	抜消	燃料 ガソリン	デモセル ハイブリッド ()	後部座席用品 () 車・取説説明書等 ()																					
走行 ★ 6 4 0 0 0	マイル	シフト		AT																					
外装色 ホワイト (0)	カラーメ AG・G・WAG・()	内装色 その他																							
()	左・(B) ディアラー・運行	ナリヤクス利	5人	PS	⑦	⑧	サンルーフ	革シート																	
セールスポイント	14,170円		税別	エアロパック	ABS	ナビ	TV	キーレス																	
検査記入欄																									
				修復歴 A 無 <table border="1" style="width:100%;"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ・凹み</td><td>B</td><td>キズ・ヘコみ</td><td>D</td><td>ぬれさび・サビ</td><td>G</td><td>ガラスのキズ</td></tr> <tr> <td>W</td><td>腐蝕跡</td><td>S</td><td>サビ</td><td>C</td><td>変形</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td></tr> </table> 登録年月日: 月 日 家でなくても可 車体番号: AXUP85-0001734						A	キズ	U	ヘコみ・凹み	B	キズ・ヘコみ	D	ぬれさび・サビ	G	ガラスのキズ	W	腐蝕跡	S	サビ	C	変形
A	キズ	U	ヘコみ・凹み	B	キズ・ヘコみ	D	ぬれさび・サビ	G	ガラスのキズ																
W	腐蝕跡	S	サビ	C	変形	X	交換済	XX	交換済																