

2023 Toyota Prius Z		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 6AA-MXWH60	DISPLACEMENT 1,986 cc		
YEAR / REG. 2023/11	MILEAGE 14,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Sedan		
CHASSIS NO. MXWH60-4050504	DIMENSIONS (L X W X H) 460 × 178 × 143 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Parking Assist (Auto Steering) Side Camera 360° Camera		Power Tailgate Adaptive Cruise Control Front Camera Back Camera Navigation System	
INSPECTOR REPORT			
Exterior: Noticeable scratches and dents have been repaired, but minor scratches and dents remain. Interior: Some noticeable stains are present in parts. Frame: No abnormalities in the structural components.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグレード鑑定/JAAA鑑定証の評価と下記記載の評価は真となります

初年度登録 R5 11月	メーカー トヨタ	ドア枚数 5	ボディ形状 セダン	評価点 4
車名 プリウス	グレード Z			
車種 自家用	型式 6AA-MXWH60	年式 2000	グレード ハイブリッド	内装 B
年式 -年-月-日	走行 14,000 km	駆動 FF	変速機 AC	重量 Kg
先代車 アテュード プラウズ	カラーNo.	リサイクル料 12,250円	車体番号 MXWH60-4050504	
()	シフト インパネ	AT	乗車定員 5人	長さ cm
諸口送り込 (保証書・取扱説明書等)	ディーラー D10326/11715			
装備 ① ② ③ サルーフ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿	ディーラー D10326/11715			
セーリングポイント	ディーラー D10326/11715			
パワーシートバックカメフラム機構防止システム(E S-C) 運転席エアバック/後部座席システム(S マートキーレスエントリー(A B S) 電子 エアバック/サイドエアバック/モーター/ビ クルセディン/運転席/後部座席/ブレーキ/アクセル/フ グリップ/シートヒーター/シートエアコン/電 気リアゲート/デュアルブレーキ/運転席/後部座 席/カメラ/フロントカメラ/サイドカメラ	ディーラー D10326/11715			
常設員記入欄	ディーラー D10326/11715			
ボダージュレベルに関する注意事項 ※は記号のみ ※は1 ※は2 ※は3 ※は4 ※は5 ※は6 ※は7 ※は8 ※は9 ※は10 ※は11 ※は12 ※は13 ※は14 ※は15 ※は16 ※は17 ※は18 ※は19 ※は20 ※は21 ※は22 ※は23 ※は24 ※は25 ※は26 ※は27 ※は28 ※は29 ※は30 ※は31 ※は32 ※は33 ※は34 ※は35 ※は36 ※は37 ※は38 ※は39 ※は40 ※は41 ※は42 ※は43 ※は44 ※は45 ※は46 ※は47 ※は48 ※は49 ※は50 ※は51 ※は52 ※は53 ※は54 ※は55 ※は56 ※は57 ※は58 ※は59 ※は60 ※は61 ※は62 ※は63 ※は64 ※は65 ※は66 ※は67 ※は68 ※は69 ※は70 ※は71 ※は72 ※は73 ※は74 ※は75 ※は76 ※は77 ※は78 ※は79 ※は80 ※は81 ※は82 ※は83 ※は84 ※は85 ※は86 ※は87 ※は88 ※は89 ※は90 ※は91 ※は92 ※は93 ※は94 ※は95 ※は96 ※は97 ※は98 ※は99 ※は100				
クオリティグレード説明 外装: 気になるキズやヘコミは補修済み ですが、小さなキズやヘコミが残って います。 内装: 気になる汚れ等が、部分的にあり ます。 動燃器: 青枠部位に異常はありません。	ディーラー D10326/11715			