


2023 Toyota Roomy Custom Custom G		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-M900A	DISPLACEMENT 996 cc		
YEAR / REG. 2023/10	MILEAGE 28,772 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Purple	BODY TYPE Sedan		
CHASSIS NO. M900A-1085714	DIMENSIONS (L X W X H) 371 × 167 × 174 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Navigation System		Power Sliding Doors (Both Sides) (Both... Adaptive Cruise Control	
INSPECTOR REPORT			
Minor exterior scratches/scuffs, light interior dirt/stains.			

ORIGINAL JAPANESE AUCTION SHEET

R5 / 10月		メーカー トヨタ		ドア数 5	ボディ形状 セダン	年価点 3.5
車名 ルーミー		グレード カスタムG		駆動区分 4WD	4WD	
車種 自家用・その他 ()	排気量 1000 cc	型式 5BA-M900A	通称 5BA	年価点 (A)・B・C		
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼルの ()	後日選り込み (保証書・取扱説明書等)			
走行 28,772 km	AT					
外装色 パープル	カラーNo. P19	AG・BG・WAG・ ()	装備品のみ O印 を記入			
内装色 クロ	乗車定員 5 人	()	()	()	()	()
左・前・後 入庫日 9,410円	ディーラー 進行	リサイクル料	エコパック	ナビ	キーレス	
セールスポイント ★クルーズコントロール！★360° カメラ！★バックカメラ！★ドライブレコーダー！★パワースライドドア！						
検査記入欄 外装細かいIA・内装薄い汚れ			修復歴 有 ()			
			A キズ U ヘッドライト B キズ・ヘッド P 熱劣化・サビ Q ガラスキズ W 補修 S サビ C 腐食 X 交換 Y 交換 Z 交換 車検No. 月 日 までに名義できる方 車体番号 M900A-1085714			
FR トビ石	傷A	ワレ	外装 小	ホイール	エアロ	シリアル No.
内装	ヨゴレ	シミ	ヤブレ	コゲ	オーディオ穴	スレ
			長さ cm	幅 cm	高さ cm	最大積載量 kg