

2023 Toyota Roomy X		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE M900A	DISPLACEMENT 996 cc		
YEAR / REG. 2023/03	MILEAGE 22,822 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Minivan		
CHASSIS NO. M900A-1033522	DIMENSIONS (L X W X H) 370 × 167 × 174 cm		
SALES POINTS			
Pre-Collision Braking		Back Camera	
INSPECTOR REPORT			
Exterior has noticeable scratches and dents. Interior has some noticeable stains. No abnormalities in the frame.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 R5/3月	メーカー トヨタ	ドア数 5	ボディ形状 ミニバン/ワンボックス	評価点 4
車名 ルーミー	グレード X			
車種 自家用	形式 M900A	排気量 1000	燃料 ガソリン	内装 B
年 22	月 8	日 22	走行 AC	重量 Kg
外装色 ブラックマイカメタリック	カラーNo. ()	リサイクル料 9,410円	車両番号 M900A-1033522	
シフト インパネ	AT	乗車定員 5人	長さ cm	高さ cm

後付品
(保証書・取扱説明書等)

装備
AW サルーフ ホット
ナビ TV キーレス

セールスポイント
バックカメラ/ETC横滑り防止装置
(ESC)/運転席エアバック/後座防
止システム/スマートキー/キーレスエ
ントリー/A B S/助手席エアバック/フ
ンセグTV/衝突被害軽減ブレーキ/衝
突安全ボディ/アイドリングストップ

査定員記入欄

※ダメージレベルに関する注意事項
ダメージは記号のみ
小は1 中は2 大は3
※ダメージレベルはA
※ダメージレベルはB
※ダメージレベルはC
※ダメージレベルはD
※ダメージレベルはE
※ダメージレベルはF
※ダメージレベルはG
※ダメージレベルはH
※ダメージレベルはI
※ダメージレベルはJ
※ダメージレベルはK
※ダメージレベルはL
※ダメージレベルはM
※ダメージレベルはN
※ダメージレベルはO
※ダメージレベルはP
※ダメージレベルはQ
※ダメージレベルはR
※ダメージレベルはS
※ダメージレベルはT
※ダメージレベルはU
※ダメージレベルはV
※ダメージレベルはW
※ダメージレベルはX
※ダメージレベルはY
※ダメージレベルはZ

クオリティグレード説明
外装:気になるようなキズやヘコミ
があります。
内装:気になる汚れ等、部分的に
あります。
修復歴:骨格部位に異常はありません。

車両状態の検閲は、停止状態で実施できる範囲で行っています。