

2023 Volkswagen VW Golf 5HB eTSI R-Line		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3AA-CDDFY	1,497 cc		
YEAR / REG.	MILEAGE		
2023/07	19,120 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Hybrid (Petrol)	Right		
EXTERIOR COLOR	BODY TYPE		
White	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WVWZZZCD3PW195986	430 × 179 × 148 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Adaptive Cruise Control		Back Camera	
Navigation System			
INSPECTOR REPORT			

初年度登録	メーカー フォルクスワーゲン	トヨタ車種 5	旧タイプ車種 コンパクトハッチバック	評価点 4.5																																																		
R5 / 7月	車名 ゴルフ	グレード e T S I Rライン	駆動区分 2WD 4WD																																																			
車庫 自家用・その他 ()	排気量 1500 cc	型式 3AA-CDDFY	選装品 型式	内装 A・B・C																																																		
車検 - - 年 / 月 / 日	燃料 ガソリン	ディーゼル	後日選り品 (色・書・取扱説明書 等)																																																			
走行 19,120 km	シフト AT																																																					
外装色 ホワイト	カラーNo.	エアコン AG・AGC・WAG・()	新装品のみ O印 を記入																																																			
()	内装色	基準定員 5人	ABS	革シート																																																		
ハシ 左・右	輸入 国産	走行 14,510円	ABS	TV																																																		
セールスポイント		修復歴 有 ()																																																				
プッシュスタート、クルーズコントロール、バックカメラ																																																						
検査記入欄		<table border="1"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>ヘコみ割れ</td> <td>B</td> <td>キズ・ヘコみ</td> <td>P</td> <td>色あせ・汚れ</td> <td>G</td> <td>ガラスキズ</td> </tr> <tr> <td>W</td> <td>修繕跡</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> </tr> <tr> <td colspan="9">登録No.</td> <td>名義主</td> </tr> <tr> <td colspan="9">月 日</td> <td>までに変更できる方</td> </tr> <tr> <td colspan="9">車体番号</td> <td>WVWZZZ CD3PW195986</td> </tr> </table>			A	キズ	U	ヘコみ割れ	B	キズ・ヘコみ	P	色あせ・汚れ	G	ガラスキズ	W	修繕跡	S	サビ	C	腐食	X	交換済	XX	交換済	登録No.									名義主	月 日									までに変更できる方	車体番号									WVWZZZ CD3PW195986
A	キズ	U	ヘコみ割れ	B	キズ・ヘコみ	P	色あせ・汚れ	G	ガラスキズ																																													
W	修繕跡	S	サビ	C	腐食	X	交換済	XX	交換済																																													
登録No.									名義主																																													
月 日									までに変更できる方																																													
車体番号									WVWZZZ CD3PW195986																																													
<table border="1"> <tr> <td>PW</td> <td>7</td> <td>備A</td> <td>フレ</td> <td>外装</td> <td>小</td> <td>エアロ</td> </tr> <tr> <td></td> <td>A</td> <td>G</td> <td></td> <td></td> <td>A</td> <td>フレ</td> </tr> </table>		PW	7	備A	フレ	外装	小	エアロ		A	G			A	フレ	<table border="1"> <tr> <td>シリアル</td> <td>No.</td> <td>車種</td> </tr> <tr> <td></td> <td></td> <td></td> </tr> </table>			シリアル	No.	車種																																	
PW	7	備A	フレ	外装	小	エアロ																																																
	A	G			A	フレ																																																
シリアル	No.	車種																																																				
<table border="1"> <tr> <td>内装</td> <td>シロ</td> <td>ヤブレ</td> <td>コゲ</td> <td>コグス</td> <td>オーディオ</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </table>		内装	シロ	ヤブレ	コゲ	コグス	オーディオ							<table border="1"> <tr> <td>長さ</td> <td>幅</td> <td>高さ</td> <td>最大積載量</td> </tr> <tr> <td>cm</td> <td>cm</td> <td>cm</td> <td>kg</td> </tr> </table>			長さ	幅	高さ	最大積載量	cm	cm	cm	kg																														
内装	シロ	ヤブレ	コゲ	コグス	オーディオ																																																	
長さ	幅	高さ	最大積載量																																																			
cm	cm	cm	kg																																																			