

2024 Alfa Romeo Giulia Veloce		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3BA-95220	DISPLACEMENT 1,995 cc		
YEAR / REG. 2024/09	MILEAGE 11,000 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Sedan		
CHASSIS NO. ZAREAELN6P7679528	DIMENSIONS (L X W X H) 466 × 187 × 144 cm		
SALES POINTS			
Alloy Wheels Power Seats (Front) Adaptive Cruise Control Navigation System		Leather Seats (Leather) Pre-Collision Braking Back Camera harman/kardon (900W14SP)	
INSPECTOR REPORT			
Driver's seat has minor wrinkles/wear.			

国名登録番号		メーカー アルファロメオ		ドアクラス 4		ボディタイプ セダン		評価点 5	
R6 / 9月		ジュリア		ヴェローチェ		駆動方式 2WD 4WD			
車種 自乗用・その他（ ）	排気量 cc	型式 3B8-95220	型式 内装 A・B・C						
年次 9年9月	検出 燃料 ディーゼル バルブリッド（ ）	後付部品名（保証書・取扱説明書等）							
走行 11万000km	シフト フロア 8 AT								
外装色 Alfa White（ ）	エンジン Qd・AGG・WAG・（ ）	新着品のみ O印を記入							
() 左・右・両 Z 左・右・両 Z	内装色 ブラックレッド 5人	標準装備 17,380円	オプション エディック	S	G	A	サンルーフ	ナビ	TV
セルズポイント									
本革シート/パワーシート/ワンオーナー/バックカメラ/ ETC/横滑り防止装置(E S C)/運転席エアバック/盗難 防止システム/スマートキー/レスエントリー/A B S/ 助手席エアバック/サイドエアバック/衝突被害軽減ブ レーキ/スタートヒーター									
検査記入欄									
運転席シートショウズレ小あり									
			修復歴 有。(S)						
			A キズ U ヘッドランプ B キズへんじ H 炎傷やヤけど D ガラスキズ W 補修跡 G ヤビ C 腐食 X 交換部 P 交換部 XX 交換部						
			登録年月日 月 日 家でに名でせする						
			型式 登録番号 ZAREAEINP67679528						
			PW トボ石 傷A ウレ 汚損 小 A・U A・曲 A・ワレ エアロ シリアル No.						
			内装 ボゴレ シモ ヤブレ コガ コガタ オーディオ スレ						