

2024 Audi Audi A4 35 TFSI S line		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3AA-8WDEM	1,984 cc		
YEAR / REG.	MILEAGE		
2024/09	14,400 km		
DOORS	SEATS		
4	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
White	Station Wagon		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WAUZZZF47RA056159	477 × 185 × 141 cm		
SALES POINTS			
Alloy Wheels		Power Seats (Front)	
Leather Seats (Alcantara, Leather (befor...		Pre-Collision Braking	
Adaptive Cruise Control		Back Camera	
360° Camera		Navigation System	
INSPECTOR REPORT			
Small wrinkles on seats, minor damage on pillar trim, minor damage on console, small stone chip on front windshield.			

新車登録		メーカー アウディ		ドアクロック 5		ステーションワゴン		評価点 5																					
R6 / 9月		車名 A 4 アパント		グレード 35 TFSI ライン		駆動方式 2WD 4WD																							
		年式 3000 CC		型式 3AA-8WDEM		運転形式		内装 A・⑨・C																					
車種 自家用 ・ その他 ()		排気量		燃料 ガソリン		ギヤーステアリング マニュアル		備考欄 後部座席は（保証書・取扱説明書等）																					
車検 9年9月		検出 年月		燃費 リッター		エンジン シフト																							
走行 14,400 km		カラー フロア 7 AT		エアコン		オーディオ FM・AM・WAG・()																							
外観色 グレイシアホワイトメタリック		カーナビ ()		内装色 ()		新着品のみ O印 を記入																							
リム ()		左・右 ()		乗人数 5人		オプション P・S・M・X・TV・⑩		車シート 革シート																					
セルスポイント		輸入区分 G		運行 15,190円		販売店 エフック																							
3 60度カメラ / OPAW / レーンアシスト / サイドアシスト / ACC / スマホインターフェース / アンビエンライト / マトリクスLED / ATトランク / Vコックピット / ナビ / シートメモリー																													
検査記入欄																													
★ A I S 検査済 シートしわ小 ビラー内強A小 コンソールA小 Fガラス飛び石小																													
修歴 有 ()																													
<table border="1" style="width: 100%;"> <thead> <tr> <th>W</th> <th>補修箇所</th> <th>U</th> <th>へこみひずみ</th> <th>B</th> <th>キズへこみ</th> <th>P</th> <th>変色傷・汚れ</th> <th>G</th> <th>ガラスキズ</th> </tr> </thead> <tbody> <tr> <td></td> <td>S</td> <td>サビ</td> <td>腐食</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> <td></td> <td>変質*</td> </tr> </tbody> </table> 登録地 〃 月 日 家でに名義を移す 車体番号 MAUZZZ7FAR056159 新車 製造 国産 輸入 国産 輸入 最大積載量										W	補修箇所	U	へこみひずみ	B	キズへこみ	P	変色傷・汚れ	G	ガラスキズ		S	サビ	腐食	X	交換済	XX	交換済		変質*
W	補修箇所	U	へこみひずみ	B	キズへこみ	P	変色傷・汚れ	G	ガラスキズ																				
	S	サビ	腐食	X	交換済	XX	交換済		変質*																				