

2024 BMW BMW X1 M35i xDrive		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
12EF20	1,998 cc		
YEAR / REG.	MILEAGE		
2024/09	5,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
White	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WBA12EF0105003217	450 × 185 × 163 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Power Tailgate		Power Seats (Front)	
Pre-Collision Braking		Adaptive Cruise Control	
Parking Assist (Auto Steering)		Front Camera	
Side Camera		Back Camera	
360° Camera		Navigation System	
harman/kardon Hi-Fi Speaker System (2...			
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

年式登録番号 R6 / 9月	メーカー BMW	ドア数 5	ボディ形状 SUV/クロカン	評価点 5
車名 X 1	グレード M35i xDrive	駆動方式 2WD	燃費区分 4WD	
車種 自家用・その他 ()	排気量 2000 cc	型式 12EF20	登録式 (A)・B・C	
年 9	月 9	日 9	扶養 なし	ディーゼル なし
走行 5,000 km	インパネ	AT	後付選用品 (保証書・取扱説明書等)	
外装色 アルビノ・ホワイト (ソリッド・カラー)	カラーNo. ()	エアコン (Qd・AAG・WAG・()	新選用品のみ・O印を記入	
内装色 ()	乗車定員 5人	PS	サンルーフ	革シート
左・前・後 左・前・後	走行 17,210 km	ナビ付	TV	その他
セールスポイント				
パワーシート/バックカメラ/ETC/横滑り防止装置 (ESC) /運転席エアバック/スマートキー/キーレスエントリー/A B S /助手席エアバック/H D Dナビ/衝突被害軽減ブレーキ/4WD/ターボ/シートヒーター/電動リアゲート/全周周カメラ/フロントカメラ/サイドカメラ				
修復歴 有・6				
検査記入欄				
A キズ B 凹み C 傷 D 汚れ E 変色 F 変形 G 欠損 H 変質 I 変色 J 変質 K 変色 L 変質 M 変色 N 変質 O 変色 P 変質 Q 変色 R 変質 S 変色 T 変質 U 変色 V 変質 W 変色 X 変色 Y 変色 Z 変色				
名義中				
月 日 まで				
WBA12EF0105003217				
内装 トビ石	外装 メタ	小 A・U	大 A・U	その他 A・U
内装 メタ	外装 メタ	小 A・U	大 A・U	その他 A・U