

2024 Honda Step Wagon Spada Spada		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-RP6	DISPLACEMENT 1,496 cc		
YEAR / REG. 2024/03	MILEAGE 24,215 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Minivan		
CHASSIS NO. RP6-1119329	DIMENSIONS (L X W X H) 483 × 175 × 184 cm		
SALES POINTS			
Alloy Wheels Power Sliding Doors (Both Sides) (Both... Pre-Collision Braking Navigation System		Leather Seats Power Tailgate Adaptive Cruise Control	
INSPECTOR REPORT			
Small tears/rips on seats, minor exterior scratches.			

前年登録額		メーカー		ホンダ		ドア数		5		ボディ形式		ミニバンワンボックス		駆動方式		4WD		新車価		9.0万円																					
R6 /		3月		ステップワゴンスパークス		グレード		スーパーダ		燃費(市街地)		18.0km/L		燃費(高速)		24.0km/L				9.0万円																					
車種		自動車用・その他		排気量		1500cc		型式		5BA-RP6		運転形式		AT		A・B・C																									
車検		9年2月		抜消		燃料		ガソリン		ディーゼル		後日送り品		()																											
走行		24,215km		インパネ		AT		Sキー																																	
外装色		クロ		(PB93P)		エンボス		AD・GD・WAD・()				新着商品のO印を記入																													
()		()		内装色		標準装備		7人		()		()		()		サンルーフ		()		()																					
左・右		左・右		ドライバー		乗行		12,310円		税別		エアロパック		ABS		()		()		()																					
セーレスポイント																																									
ワンオーナー、純正9インチナビ、フルセグTV、ホンダセンシング、バックカメラ、両側パワーライドドア、ETC、プッシュスタート、スマートキー、LEDヘッドライト、ハーフレザーシート、シートヒーター、Honda CONNECT for Gathers+ナビ装着用スペシャルPKG																																									
検査記入欄																																									
シート小切れ・破れ 外装小傷有り																																									
修理履歴 有。() <table border="1"> <thead> <tr> <th>A</th> <th>ボディ</th> <th>U</th> <th>へっぺりヤバ</th> <th>B</th> <th>ボディへっぺり</th> <th>F</th> <th>軸受けヤバ</th> <th>G</th> <th>ガスケット</th> </tr> </thead> <tbody> <tr> <td>W</td> <td>補修跡</td> <td>S</td> <td>サビ</td> <td>C</td> <td>変質</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> </tr> </tbody> </table> 名義人 月 日 家で名義者である 車体番号 RP6-1119329																						A	ボディ	U	へっぺりヤバ	B	ボディへっぺり	F	軸受けヤバ	G	ガスケット	W	補修跡	S	サビ	C	変質	X	交換済	XX	交換済
A	ボディ	U	へっぺりヤバ	B	ボディへっぺり	F	軸受けヤバ	G	ガスケット																																
W	補修跡	S	サビ	C	変質	X	交換済	XX	交換済																																
<table border="1"> <thead> <tr> <th>PW</th> <th>トギ足</th> <th>備A</th> <th>フレ</th> <th>内装</th> <th>小</th> <th>オイル</th> <th>エアロ</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td>()</td> <td>()</td> <td>()</td> </tr> </tbody> </table>																						PW	トギ足	備A	フレ	内装	小	オイル	エアロ						()	()	()				
PW	トギ足	備A	フレ	内装	小	オイル	エアロ																																		
					()	()	()																																		