

|                                                                                                                                                                                                                            |                                              |                                                                                           |               |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|-------------------------------------------------------------------------------------------|---------------|
| 2024 MITSUBISHI Delica D2 HYBRID MZ<br>All-around Camera Package                                                                                                                                                           |                                              | OVERALL<br>4                                                                              |               |
|                                                                                                                                                                                                                            |                                              | EXTERIOR<br>-                                                                             | INTERIOR<br>- |
| MODEL CODE<br>5AA-MB37S                                                                                                                                                                                                    | DISPLACEMENT<br>1,242 cc                     |                                                                                           |               |
| YEAR / REG.<br>2024/04                                                                                                                                                                                                     | MILEAGE<br>41,000 km                         |                                                                                           |               |
| DOORS<br>5                                                                                                                                                                                                                 | SEATS<br>5                                   |                                                                                           |               |
| DRIVETRAIN<br>2WD (FF)                                                                                                                                                                                                     | TRANSMISSION<br>AT                           |                                                                                           |               |
| FUEL<br>Hybrid (Petrol)                                                                                                                                                                                                    | STEERING<br>Right                            |                                                                                           |               |
| EXTERIOR COLOR<br>Other                                                                                                                                                                                                    | BODY TYPE<br>Minivan                         |                                                                                           |               |
| CHASSIS NO.<br>MB37S-112622                                                                                                                                                                                                | DIMENSIONS (L X W X H)<br>379 × 165 × 175 cm |                                                                                           |               |
| SALES POINTS                                                                                                                                                                                                               |                                              |                                                                                           |               |
| Alloy Wheels<br>Pre-Collision Braking<br>360° Camera                                                                                                                                                                       |                                              | Power Sliding Doors (Both Sides) (Both...<br>Adaptive Cruise Control<br>Navigation System |               |
| INSPECTOR REPORT                                                                                                                                                                                                           |                                              |                                                                                           |               |
| Exterior: While noticeable scratches and dents have been repaired, small scratches and dents remain. Interior: There are some noticeable stains, etc., in parts. Repair history: No abnormalities in the frame components. |                                              |                                                                                           |               |

[illegible]