

| 2024 MITSUBISHI Delica D5 2.2 P 4WD                                                           |                        | OVERALL                                   |          |
|-----------------------------------------------------------------------------------------------|------------------------|-------------------------------------------|----------|
|                                                                                               |                        | 4.5                                       |          |
|                                                                                               |                        | EXTERIOR                                  | INTERIOR |
|                                                                                               |                        | -                                         | -        |
| MODEL CODE                                                                                    | DISPLACEMENT           |                                           |          |
| 3DA-CV1W                                                                                      | 2,267 cc               |                                           |          |
| YEAR / REG.                                                                                   | MILEAGE                |                                           |          |
| 2024/11                                                                                       | 6,903 km               |                                           |          |
| DOORS                                                                                         | SEATS                  |                                           |          |
| 5                                                                                             | 8                      |                                           |          |
| DRIVETRAIN                                                                                    | TRANSMISSION           |                                           |          |
| 4WD                                                                                           | AT                     |                                           |          |
| FUEL                                                                                          | STEERING               |                                           |          |
| Diesel                                                                                        | Right                  |                                           |          |
| EXTERIOR COLOR                                                                                | BODY TYPE              |                                           |          |
| Other                                                                                         | Other                  |                                           |          |
| CHASSIS NO.                                                                                   | DIMENSIONS (L X W X H) |                                           |          |
| CV1W-5018916                                                                                  | 480 × 179 × 187 cm     |                                           |          |
| SALES POINTS                                                                                  |                        |                                           |          |
| Alloy Wheels                                                                                  |                        | Power Sliding Doors (Both Sides) (Both... |          |
| Power Tailgate                                                                                |                        | Pre-Collision Braking                     |          |
| Adaptive Cruise Control                                                                       |                        | Front Camera                              |          |
| Side Camera                                                                                   |                        | Back Camera                               |          |
| 360° Camera                                                                                   |                        | Navigation System                         |          |
| INSPECTOR REPORT                                                                              |                        |                                           |          |
| Minor AU damage, minor A on interior panel, scratches on door mirror, jack included in tools. |                        |                                           |          |