

2024 MITSUBISHI Delica D5 P		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-CV1W	DISPLACEMENT 2,267 cc		
YEAR / REG. 2024/01	MILEAGE 53,845 km		
DOORS 5	SEATS 8		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Minivan		
CHASSIS NO. CV1W-5002829	DIMENSIONS (L X W X H) 480 × 180 × 188 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Both...	
Power Tailgate		Pre-Collision Braking	
Adaptive Cruise Control		Front Camera	
Side Camera		Back Camera	
Navigation System			
INSPECTOR REPORT			
Interior: Medium scuffs on headliner, minor scuffs on seats, minor A-grade damage on door trim and console, medium A-grade damage on cargo area trim, minor scuffs on steering wheel. Exterior: Repair marks on left quarter panel, front bumper, and rear bumper. Stone chips around the front and on the front glass. Major A-grade damage on rear gate trim.			

ORIGINAL JAPANESE AUCTION SHEET

車種 R6	メーカー 三菱	ドア数 5	ボディ形状 ミニバンワンボックス	評価点 4
1月	車名 デリカD:5	P	駆動方式 2WD	
車庫 自家用・その他()	排気量 2200	型式 3DA-CV1W	登録区分 A・B・C	
走行 53,845	燃料 ガソリン	変速機 AT	後付選り品 (色塗装・取付品等)	
外装色 クロ	カラーNo. X42	エンジン Qd・AAG・WAG・()	装備品のみ・O印を記入	
内装色 ()	乗車定員 8人	PS	PW	サンルーフ
左・前 左・前 左・前	ディーラー 走行	13,750円	エレクトロ	その他
セールスポイント				
Bカメラ、ETC、マット				
修復歴 有・6				
検査記入欄				
天張りスレ中、シートスレ小、ドア内張A小、荷室内張A中、ハンドルスレ小、コンソールA小、左クォタ修理跡、Fバンパー修理跡、F走り飛び石、Fガラス飛び石中、リアゲート内張A大、Rバンパー修理跡				
名変中				
月 日 までに名変せしめる方				
車体番号 CV1W-5002829				
車種 R6				
メーカー 三菱				
型式 3DA-CV1W				
排気量 2200				
変速機 AT				
駆動方式 2WD				
登録区分 A・B・C				
ボディ形状 ミニバンワンボックス				
ドア数 5				
評価点 4				