

2024 Toyota Crown Crossover Z		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 6AA-AZSH35	DISPLACEMENT 2,487 cc		
YEAR / REG. 2024/11	MILEAGE 17,304 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE SUV		
CHASSIS NO. AZSH35-4023331	DIMENSIONS (L X W X H) 493 × 184 × 154 cm		
SALES POINTS			
Alloy Wheels Leather Seats (Leather) Pre-Collision Braking Parking Assist (Auto Steering) Side Camera Navigation System		Glass Roof Power Seats (Front) Adaptive Cruise Control Front Camera Back Camera Toyota Premium Sound System (10 Spe...	
INSPECTOR REPORT			
Seat and steering wheel show wear. Minor wear/stains on headliner, trim, exterior housing, and interior parts. Minor issues with genuine courtesy lamp and brake pedal cover. Front windshield has a stone chip. Interior shows dirt, stains, tears, burns, burn holes, and scuffs on the audio panel.			

ORIGINAL JAPANESE AUCTION SHEET

車種 R6 11月	メーカー トヨタ	ドア数 5	ボディ形状 SUV/クロカン	評価点 4.5
車名 クラウンクロスオーバー	グレード Z	駆動方式 2WD	変速機 AT	
車庫 自家用・その他 ()	排気量 2480 cc	型式 6AA-AZSH35	登録区分 A・⑤・C	
年 9	月 1	日 1	扶養 なし	ディーゼル なし
走行 17,304 km	燃料 ハイブリッド	シフト AT	後付選用品 ()	
外装色 その他 (2XZ)	エアコン AG・AC・WAG・ ()	新車登録 5人	PS	サンルーフ
内装色 その他	乗車定員 5人	PS	ABS	ナビ
左・右 左	輸入 国産	ディーラー 直営	14,930円	キーレス
セールスポイント				
パノラマガラスルーフ レーダークルーズコントロール 置くだけ充電 シートヒーター ベンチレーション HUD BSM				
検査記入欄				
A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損				
名義中				
月 日 まで				
AZSH35-4023331				
0 kg				