

|                                                  |  |                                |          |
|--------------------------------------------------|--|--------------------------------|----------|
| 2025 BMW_Mini BMW Mini 3HB Cooper S Classic Trim |  | OVERALL                        |          |
|                                                  |  | 6                              |          |
|                                                  |  | EXTERIOR                       | INTERIOR |
|                                                  |  | -                              | -        |
| MODEL CODE                                       |  | DISPLACEMENT                   |          |
| 3BA-22GD20                                       |  | 1,998 cc                       |          |
| YEAR / REG.                                      |  | MILEAGE                        |          |
| 2025/12                                          |  | 3,100 km                       |          |
| DOORS                                            |  | SEATS                          |          |
| 3                                                |  | 4                              |          |
| DRIVETRAIN                                       |  | TRANSMISSION                   |          |
| 2WD (FF)                                         |  | AT                             |          |
| FUEL                                             |  | STEERING                       |          |
| Petrol                                           |  | Right                          |          |
| EXTERIOR COLOR                                   |  | BODY TYPE                      |          |
| Pearl White                                      |  | Hatchback                      |          |
| CHASSIS NO.                                      |  | DIMENSIONS (L X W X H)         |          |
| WMW22GD0002X55933                                |  | 388 × 175 × 146 cm             |          |
| SALES POINTS                                     |  |                                |          |
| Alloy Wheels                                     |  | Pre-Collision Braking          |          |
| Adaptive Cruise Control                          |  | Parking Assist (Auto Steering) |          |
| Front Camera                                     |  | Side Camera                    |          |
| Back Camera                                      |  | 360° Camera                    |          |
| Navigation System                                |  |                                |          |
| INSPECTOR REPORT                                 |  |                                |          |
| AIS inspected, main equipment confirmed OK.      |  |                                |          |

[illegible]