

2025 BMW_Mini BMW Mini Countryman Countryman C Classic Trim		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3BA-12GA15	1,498 cc		
YEAR / REG.	MILEAGE		
2025/08	5,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WMW12GA0907T30455	445 × 185 × 166 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Power Seats (Front)		Pre-Collision Braking	
Adaptive Cruise Control		Parking Assist (Auto Steering)	
Front Camera		Side Camera	
Back Camera		Navigation System	
INSPECTOR REPORT			
Minor A-grade damage on pillar trim.			

初年度登録	メーカー Nissan	車種 MINI	ドア数 2	ボディ形状 SUW/クローン	評価点 5		
R7 / 8月	車名 MINI	グレード カントリーマン クラシック・トリム	駆動方式 2WD 4WD		5		
車速 自動用 ・ その他（ ）	排気量 1500	型式 CC	3BA-12GA15	過熱形式	内装 A・B・C		
年次 10年8月	抜出 英制 メーター マイル	燃料 ガソリン	デゼール	最低燃費値 () km/l	() km/h		
走行 1万5千000km	エンジン インパネ 7 AT			保証書、取扱			
外観色 ブルーメタリック	カラーNo. AG・WG・WAG・()			新着品のみのO印を記入			
ブレーキング・ブルメタリック	内装色 5人			サンルーフ	革シート		
()	左・右 Zー	運行 乗客のみ	16,660円	エアバッグ	NAB TV		
セルスポイント							
キーレスエントリー/A B S/運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/衝突被害軽減ブレーキ/E TC/スマートキー/盗難防止システム/ オートクルーズコントロール/横滑り防止装置 (E S C) / パワーステアリング/ヒーター/電動リアゲート/フロントカメラ/サイドカメラ/バックカメラ/障害物センサー/パーキングアシスト							
検査記入欄							
ビラー内張小A							
修復歴 有。()							
AW キズ U ヘッドオンキズ B キズヘッダ P 側面キズ X 後部損傷 XX 大規模損傷 W 軽微損傷 S サブ C 腐食 Y 変形 Z 欠陥							
登録地 〇 月 日 家でに名義で所有する							
車両番号 MWM12G A0907T3045S							
PW トボ石	備A	フレ	内装	小 ①	ホイール A・B・A・ス	エプロン No.	シリアル No.
内装	フロア	シミ	ヤブレ	コサ	コザウ	オーディオ	スレ