

2025 DS Automobiles DS9 Opera PureTech		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE X835G06	DISPLACEMENT 1,598 cc		
YEAR / REG. 2025/12	MILEAGE 4,000 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Sedan		
CHASSIS NO. VR1X25GGRN2802613	DIMENSIONS (L X W X H) 494 × 186 × 146 cm		
SALES POINTS			
Alloy Wheels		Sunroof	
Leather Seats (Nappa Leather)		Power Seats (Front)	
Pre-Collision Braking		Adaptive Cruise Control	
Parking Assist (Auto Steering)		Front Camera	
Back Camera		360° Camera	
Navigation System		FOCAL Electra (HiFi 14SP)	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

年式登録番号 R7 / 12月	メーカー DSオートモビル	ドア数 4	ボディ形状 セダン	評価点 5
車名 DS9	グレード オペラ デック	駆動方式 2WD 4WD		
車種 自家用・その他 ()	排気量 1600 cc	型式 X835G06	登録区分 A・B・C	
車検 10年12月 / 抹消	燃料 ガソリン	ディーゼル	後付選り品 (色塗装・取付品等)	
走行 10年12月 / 4,000 km	フロア フロア 8 AT			
外装色 ブロンナクレ	カラーNo.	エアコン Qd・AAG・WAG・()	新着品のみ・O印を記入	
内装色 ()	乗車定員 5人	PS・PC・AN・サロ・フ・モ		
左・前・後 左・前・後	走行 19,840 km	エ・ク・サ・フ・モ		
セールスポイント				
本革シート/パワーシート/ワンオーナー/バックカメラ/ETC/横滑り防止装置 (ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/メモリーナビ他/フルセグTV/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/ターボ/シートヒーター/シートエアコン/電動リアゲート/ミュージックプレイヤー接続可/全周囲カメラ/フロントカメラ				
検査記入欄				
A キズ B 凹み C 傷 D 汚れ E 変色 F 変形 G 故障 H 欠損 I 他				
W 補修 S サゼ C 腐食 X 交換 Y 交換済 Z 交換済				
登録年月日 月 日 年				
車検番号 VR1X25GGRN2802613				
内装 トビ石	外装 メタ	フロア フロア	小 Q・U	大 A・B・C・D・E・F・G・H・I・J・K・L・M・N・O・P・Q・R・S・T・U・V・W・X・Y・Z・0・1・2・3・4・5・6・7・8・9・10・11・12・13・14・15・16・17・18・19・20・21・22・23・24・25・26・27・28・29・30・31・32・33・34・35・36・37・38・39・40・41・42・43・44・45・46・47・48・49・50・51・52・53・54・55・56・57・58・59・60・61・62・63・64・65・66・67・68・69・70・71・72・73・74・75・76・77・78・79・80・81・82・83・84・85・86・87・88・89・90・91・92・93・94・95・96・97・98・99・100