

2025 Honda Step Wagon Spada HV eHEV Spada Premium Line Black Edition		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE RP8	DISPLACEMENT 1,993 cc		
YEAR / REG. 2025/07	MILEAGE 4,100 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE Minivan		
CHASSIS NO. RP8-1310365	DIMENSIONS (L X W X H) 483 × 175 × 185 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Adaptive Cruise Control		Power Sliding Doors (Both Sides) (Both... Pre-Collision Braking	
INSPECTOR REPORT			
Minor scratches and dents on interior and exterior, left center pillar (XX)			

初年度登録	メーカー ホンダ		ドア数 5		ボディ種類 ミニバンワンボックス		特価点 R																																																			
R7 / 7月	車名 ステップワゴン		グレード HEVスーパーデュアルインブラックエディ		駆動方式 2WD 4WD		R																																																			
車種 自家用・その他 ()	排気量 3000	型式 CC	RP8		通称形式	内装 A・B・C																																																				
年次 10年4月	抹消	燃料 ガソリン	ディーゼル		償還月数 (保証年・取扱い明言等)																																																					
走行 4,100 km	マイル	シフト オート	フロア AT																																																							
外装色 プレミアムメタリックパールホワイト		カラーNo.	エンジン Qd・A4D・W4D・()		新着品のみ O印 を記入																																																					
()		内装色 ベージュ	乗車定員 7人		EP	FP	AP	サンルーフ																																																		
シ	左・右	輸入	ディーラー	走行	31マイル/リットル	22,190円	税別	EP																																																		
セールスポイント																																																										
☆HYBRID ☆両側電動スライド ☆レーダークルーズコントロール ☆パドルシフト ☆フローティング大型ディスプレイ ☆AppleCarplay ☆パワーバックドア ☆キャブテンシート ☆ミラー型ドライブレコーダー					修復歴 0・無																																																					
検査記入欄					<table border="1"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>ヘッドランプ</td> <td>B</td> <td>キズ・へっすり</td> <td>P</td> <td>色あせ・汚れ</td> <td>G</td> <td>ガラス</td> </tr> <tr> <td>W</td> <td>傷跡</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> </tr> <tr> <td colspan="9">査察No.</td> <td>名義</td> </tr> <tr> <td colspan="9">月</td> <td>日</td> </tr> <tr> <td colspan="9">車体番号</td> <td>RP8-1310365</td> </tr> </table>				A	キズ	U	ヘッドランプ	B	キズ・へっすり	P	色あせ・汚れ	G	ガラス	W	傷跡	S	サビ	C	腐食	X	交換済	XX	交換済	査察No.									名義	月									日	車体番号									RP8-1310365
A	キズ	U	ヘッドランプ	B	キズ・へっすり	P	色あせ・汚れ	G	ガラス																																																	
W	傷跡	S	サビ	C	腐食	X	交換済	XX	交換済																																																	
査察No.									名義																																																	
月									日																																																	
車体番号									RP8-1310365																																																	
内外装小傷エウボ 左センタービラ-XX					<table border="1"> <tr> <td>FW</td> <td>ボディ</td> <td>窓</td> <td>ウレ</td> <td>外装</td> <td>小</td> <td>ホイール</td> <td>エアロ</td> <td>シリアル</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td>①・②</td> <td>③・④</td> <td>⑤・⑥</td> <td>⑦・⑧</td> </tr> <tr> <td>内装</td> <td>⑨・⑩</td> <td>⑪・⑫</td> <td>⑬・⑭</td> <td>⑮・⑯</td> <td>⑰・⑱</td> <td>⑲・⑳</td> <td>㉑・㉒</td> <td>㉓・㉔</td> </tr> </table>				FW	ボディ	窓	ウレ	外装	小	ホイール	エアロ	シリアル						①・②	③・④	⑤・⑥	⑦・⑧	内装	⑨・⑩	⑪・⑫	⑬・⑭	⑮・⑯	⑰・⑱	⑲・⑳	㉑・㉒	㉓・㉔																							
FW	ボディ	窓	ウレ	外装	小	ホイール	エアロ	シリアル																																																		
					①・②	③・④	⑤・⑥	⑦・⑧																																																		
内装	⑨・⑩	⑪・⑫	⑬・⑭	⑮・⑯	⑰・⑱	⑲・⑳	㉑・㉒	㉓・㉔																																																		