

2025 Lexus RX 350 F Sport 4WD		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 5BA-TALA15		DISPLACEMENT 2,393 cc	
YEAR / REG. 2025		MILEAGE 4,134 km	
DOORS 5		SEATS 5	
DRIVETRAIN 4WD		TRANSMISSION AT	
FUEL Petrol		STEERING Right	
EXTERIOR COLOR White		BODY TYPE SUV	
CHASSIS NO. TALA15-1010642		DIMENSIONS (L X W X H) 489 × 192 × 170 cm	
SALES POINTS			
Sunroof Power Tailgate Leather Seats (Leather, Ultrasuede) Adaptive Cruise Control Side Camera Navigation System		Alloy Wheels Power Seats (Front) Pre-Collision Braking Front Camera Back Camera Lexus RX Premium Sound System (12 s...	
INSPECTOR REPORT			
Exterior: Scratches on the right front wheel and left rear wheel, minor scratches on the left side mirror. Repair marks observed on the left front/rear door and rear fender.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 R7 / 一月	メーカー レクサス	ドア数 5	ボディ形状 SUV/クロカン	評価点 4.5
車種 自家用・その他 ()	型式 2390 cc	グレード RX	駆動方式 4WD	登録区分 2WD 4WD
車検 - - 年 / 月 / 日	燃料 ガソリン	ディーゼル	後付選用品 (保証書・取扱説明書等)	
走行 4,134 km	エンジン ハイブリッド	AT		
外装色 ホワイトノヴァガラスフレック	カラーNo. ()	エアコン ()	装備品のみ・O印を記入	
内装色 ()	乗車定員 人	PS	PW	AW
左・前 左・前	ディーラー	走行	15,700円	PS PW AW サーフ シート
セールスポイント		エアバック ABS TV キーレス		
検査記入欄		修復歴 有・6		
【車両状態】		A キズ B ハコボレ C キズ・ヘコ D 色あせ・汚れ E ガラスキズ W 腐蝕 S サビ C 磨耗 X 交換 Y 交換済		
外装 右Fホイール/左Rホイールに傷、左サイドミラーに小傷、 左F.RドアRフェンダーに補修跡が見受けられました。		名義中 月 日 まで 名義で受ける方		
内装 ()		車検番号 TALA15-1010642		
FR ()	FL ()	PR ()	PL ()	SR ()
シス	サブレ	コグ	コグス	オーディオス
489 cm	192 cm	170 cm	最大積載量 kg	