

2025 Toyota LandCruiser ZX		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3BA-VJA300W	DISPLACEMENT 3,444 cc		
YEAR / REG. 2025/06	MILEAGE 8,471 km		
DOORS 5	SEATS 7		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE SUV		
CHASSIS NO. VJA300-4197997	DIMENSIONS (L X W X H) 499 × 198 × 193 cm		
SALES POINTS			
Alloy Wheels Roof Rails Power Tailgate Pre-Collision Braking Front Camera Back Camera		Sunroof Leather Seats (Leather) Power Seats (Front) Adaptive Cruise Control Side Camera Rear Seat Entertainment (Rear Seat Ent...	
INSPECTOR REPORT			
Interior: Steering wheel scuff, seat scuff, minor trim damage, headliner dirt, general dirt, scuffs. Exterior: Light scratches, minor door mirror damage. Power window stone chip.			

ORIGINAL JAPANESE AUCTION SHEET

車種 R7	メーカー トヨタ	ドア数 5	ボディ形状 SUV/クロカン	評価点 5
6月	車名 ランドクルーザー Zx	グレード 3BA-VJ A300W	駆動方式 2WD 4WD	
車庫 自家用・その他 ()	排気量 3440 cc	型式 3BA-VJ A300W	登録式 (A)・B・C	
車検 10年6月	扶養 無	ディーゼル ハイブリッド ()	後付選用品 ()	
走行 8471 km	シフト AT	エンジン AG・WAG・ ()	新選用品のみ・O印を記入	
外装色 ホワイト	カラーNo. 090	乗車定員 7人	PS	ABS ナビ TV キーレス
左・右 左・右	ディーラー 直付	16,910円	エレクトリック	
セールスポイント				
純正ナビ 後席モニター サンルーフ クーラーボックス 電動デフロック パワーシート パワートランク ルーフレール				
検査記入欄				
内装 ステアリングホイール シートベルト ドアロック 内装色				
外装 ボディカラー ドアミラー				
修復歴 有・無				
A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損				
名義中 月 日 まで				
VJ A300-4197997				
全長 全幅 全高 最大積載量				