

2025 Toyota Yaris G		OVERALL	
		5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
5BA-MXPA10	1,490 cc		
YEAR / REG.	MILEAGE		
2025/11	6,679 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	MT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
MXPA10-2094264	395 × 170 × 150 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Adaptive Cruise Control		Back Camera	
Navigation System			
INSPECTOR REPORT			
Steering wheel wear, seat wear, trim wear (A), overall exterior wear (A), front windshield stone chip, interior dirt, stains, tears, burn marks, burn holes, audio hole, general wear.			

ORIGINAL JAPANESE AUCTION SHEET

型式 R7 11月	メーカー トヨタ	ドア数 5	ボディ形状 コンパクト/ハッチバック	評価点 5
車名 ヤリス	グレード G	駆動方式 4WD	燃費区分 4WD	
車種 自家用・その他 ()	排気量 1490 cc	型式 5BA-MXPA10	通称 5	内装 A・B・C
年 10	月 11	日 11	燃料 ガソリン	ディーゼル
走行 6,679 km	シフト MT	後付部品 ()	車検 有効	車検 有効
カラー レッド (2SR)	エンジン AG・AG・WAG ()	後付部品のみ O印 を記入	PS	サンルーフ
内装 ブラック	乗車定員 5人	ABS	ナビ	TV
走行 9,450円	リサイクル料	エアロ	ABS	ナビ
セールスポイント BSM パノラミックビューモニター 社外マフラー (HKS) 社外AW				
検査記入欄 検出故障：純正マフラー ハンドルスレ シートスレ トリムウサ 外観全体的ウサ	修復歴 有 ()			
検出故障：純正マフラー ハンドルスレ シートスレ トリムウサ 外観全体的ウサ	A キズ B へこみ C 凹み D 色あせ E 汚れ F 錆 G ガラスキズ H 変形 I 変色 J 変色 K 変色 L 変色 M 変色 N 変色 O 変色 P 変色 Q 変色 R 変色 S 変色 T 変色 U 変色 V 変色 W 変色 X 変色 Y 変色 Z 変色			
検出故障：純正マフラー ハンドルスレ シートスレ トリムウサ 外観全体的ウサ	MXPA10-2094264			
検出故障：純正マフラー ハンドルスレ シートスレ トリムウサ 外観全体的ウサ	0 kg			