

2025 Volkswagen VW Golf Variant eTSI Active		OVERALL	
		6	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3AA-CDDXDV	1,497 cc		
YEAR / REG.	MILEAGE		
2025/08	2,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Hybrid (Petrol)	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	Station Wagon		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WVWZZZCD4SW622603	464 × 179 × 149 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Pre-Collision Braking		Adaptive Cruise Control	
Back Camera		Navigation System	
INSPECTOR REPORT			

初年度登録		メーカー フォルクスワーゲン		トランスミッション 5		ボディ形状 ステーションワゴン		評価点																					
R7 / 8月		車名 ゴルフヴァリアント		グレード e T S I アクティブ		駆動方式 4WD		6																					
車種 自家用 ・ その他 ()		排気量 1500 cc		型式 3AA-CDDXDV		運転席側 左		内装 A・B・C																					
年次 10年8月		燃料 ガソリン		ディーゼル シフト ハブ		後日送り品 (色変更 ・ 取付印字等)																							
走行 2万000マイル		フロア 7 AT		スペアキー																									
外装色 ブルー		カラーNo.		エアコン AG・GAG・WAG・()		新着品のみのO印を記入																							
()		標準定員 5人		PS		AV		サンルーフ																					
エンジン 左・右・前入出力		デモ走行		リサイクル料 13,620円		エレクトロニクス		TV																					
セールスポイント		キーレスエントリー/ABS/運転席エアバック/助手席エアバック/サイドエアバック/メモリーナビ他ETC/盗難防止システム/横滑り防止装置(E.S.C)/CD/バックカメラ/定期点検記録簿																											
検査記入欄		修繕歴 有 ()																											
AIS 検査済		<table border="1"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>ヘコみ割れ</td> <td>B</td> <td>キズ・ヘコみ</td> <td>C</td> <td>色あせ・汚れ</td> <td>G</td> <td>ガラスキズ</td> </tr> <tr> <td>W</td> <td>補修跡</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換部</td> <td>XX</td> <td>交換済</td> </tr> </table>								A	キズ	U	ヘコみ割れ	B	キズ・ヘコみ	C	色あせ・汚れ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換部	XX	交換済
A	キズ	U	ヘコみ割れ	B	キズ・ヘコみ	C	色あせ・汚れ	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換部	XX	交換済																				
		登録地 月 日 までに変更できる方																											
		車体番号 WVVZZZ CD4S W622603																											
PW トピ石		備A フレ		外装		小		エアロ																					
						A・U A・曲 A・フレ																							
内装		ヨゴレ シミ		ヤブレ		コゲ コグク		オーディオ スレ																					